

Ref.	Part No	Description	Machine unit No or Subassembly description / Qty								Notes
			548810 -								
			- 01	- 02							
1	223412 49	O-ring.....	1	1							
2	37535	Ball bearing.....	1	1							
3	548051 05	Ball bearing.....	1	1							
4	543612 01	Gasket.....	1	1							
5	543619 80	Rubber buffer.....	2	2							
6	223406 29	O-ring.....	1	1							
7	73547	Seal ring.....	1	1							
8	547992 01	Packing.....	1	1							
9	548831 01	Friction element.....	4	4							
10	223406 35	O-ring.....	2	2							
11	544465 02	Loctite 242.....	1	1							
12	260169 22	Flat belt.....	1	--	--	--	--	--	--	--	50 Hz
12	260169 23	Flat belt.....	--	1	--	--	--	--	--	--	60 Hz
13	548047 80	Spindle.....	1	1							